



採取前 (A3-1)



削孔状況 (A3-1)




ボーリングバー削孔状況 (A3-1)



採取状況 (A3-1)



採取後 (A3-1)



分析状況 (A3-1)



採取前 (A4-1)



採取状況 (A4-1)



採取後 (A4-1)



採取前 (A4-a)



採取状況 (A4-a)



採取後 (A4-a)



採取前 (A4-b)



採取状況 (A4-b)



採取後 (A4-b)



採取前 (A4-c)



採取状況 (A4-c)



採取後 (A4-c)



採取前 (B4-1)



採取状況 (B4-1)



採取後（B4-1）



採取前（A5-a）



採取状況（A5-a）



採取後（A5-a）



採取前 (A5-b)



採取状況 (A5-b)



採取後 (A5-b)



採取前 (A5-c)



採取状況 (A5-c)



採取後 (A5-c)



採取前 (A7-e)



採取状況 (A7-e)



採取後 (A7-e)



採取前 (A7-f)



採取状況 (A7-f)



採取後 (A7-f)



採取前 (A8-1)



採取状況 (A8-1)



採取後 (A8-1)



採取前 (B8-1)



採取状況 (B8-1)



採取後 (B8-1)



採取前 (A10-1)



採取状況 (A10-1)

工務局
工區
圖號 500-1
1965年1月16日
測量員

採取状況 (B10-1)